

Oil Field Environmental Incident Summary

Incident: 20150223212322 **Date/Time of Notice:** 02/23/2015 21:23

Responsible Party: ONEOK Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Demicks Lake Compressor Station

Field Name:

Well File #:

Date Incident: 2/22/2015 **Time Incident:** 12:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 96

Sec: 17

Qtr:

Location Description: 3392 113th Ave NW
Keene, ND 58847

Submitted By: Jason Lyons

Received By:

Contact Person: Jason Lyons
2700 Lincoln Ave
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Gallons	30	Gallons		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no offsite impacts or immediate risks to human health or the environment.

Areal Extent:

Majority of released oil contained on compressor skid. Impacted area approx. 5 ft X 10 ft.

Potential Environmental Impacts:

There were no impacts to surface water or groundwater. Facility topsoil inside compressor building was impacted, but released material was collected with absorbent pads.

Action Taken or Planned:

Facility personnel responded immediately and released material was collected with absorbent pads.

Wastes Disposal Location: Recovered wastes will be disposed in accordance with applicable State/Federal regulations.

Agencies Involved: Karolin Rockvov - McKenzie County Emergency Manager

Updates

Date: 2/24/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. Because this is a compressor station, not an E&P location, followup is necessary.

Date: 2/25/2015 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

A compressor valve failed, and 30 gallons of compressor oil was released. The majority of the oil remained on the skid, and about five gallons came in contact with the compressor building floor. The entire release was contained in the building. Absorbent material was placed on the spill and then scraped up. Any impacted equipment was cleaned off. No further action is warranted.